Calgary Office Suite 1000, 250 - 5 Street SW, Calgary, Alberta, Canada T2P 0R4 Toll Free 1-855-297-8311 Fax 403-297-7336 www.ercb.ca

JANUARY 23, 2012

APPENDIX A: INTERWELLBORE COMMUNICATION DURING FRACTURING OPERATION EVENTS

Since 2008, almost 2,000 wells have been drilled in Alberta that utilized horizontal, multi-stage, hydraulic fracturing to enhance oil and gas recovery. Of these, more than 640 were gas wells and almost 1,300 were oil wells. The ERCB has confirmed five instances of hydraulic fracturing impacting nearby energy wells. There are no documented cases of a similar occurrence impacting water wells in Alberta.

The most recent incident occurred on Friday, January 13, 2012, when a Midway Energy Ltd. multi-stage fracturing operation appears to have impacted a nearby Wildstream Exploration Ltd. oil well. This most recent event remains under ERCB investigation.

No public safety or significant environmental impact was recorded in any of the incidents, including the most recent.

Following is a list of the five events.

Date: January 13, 2012 Owner of fractured well: Midway Energy Ltd.

Owner of impacted well: Wildstream Exploration Ltd.

Location of incident: 35 kilometres southwest of Innisfail, Alberta

Surface distance between wells: 1.2 kilometres Subsurface distance between wells: Under investigation

Fracturing oil, sand, nitrogen **Fracture fluid:**

Unconfirmed, ERCB investigation underway Volume released:

Spill cleaned. ERCB investigation underway. No public **Current status:**

safety impacts. Limited environmental impact.

Date: September 24, 2011 Owner of fractured well: Bonterra Energy Ltd. Owner of impacted well: Sword Energy

Location of incident: 30 kilometers east of Drayton Valley

Surface distance between wells: Approximately 475 metres

Subsurface distance between wells: 470 metres

Fracture fluid: Nitrogen, foam, water Volume released: Approximately 8m³

Spill cleaned up. No public safety impacts. Minimal **Current status:**

environmental impact.

Date: March 17, 2011 Owner of fractured well: Yangarra Resources Owner of impacted well: Yangarra Resources

16 kilometres north of Rocky Mountain House **Location of incident:**

Surface distance between wells: Approximately 1,500 metres

Subsurface distance between wells: 110 metres

Fracture fluid: Nitrogen, foam, water Approximately 2.3 m³ Volume released:

Spill cleaned up. No public safety impacts. Minimal **Current status:**

environmental impact.

Date: December 9, 2010 Owner of fractured well: **Bellatrix** Exploration Owner of impacted well: **Bellatrix** Exploration

Location of incident: 38 kilometres northwest of Rocky Mountain House

Surface distance between wells: Approximately 530 metres

Subsurface distance between wells: 475 metres

Nitrogen, foam, water Fracture fluid:

No liquid spill **Volume released:**

No public safety impacts. No environmental impact. **Current status:**

Date: October 19, 2009

Owner of fractured well: Talisman Energy (now owned by Advantage Oil & Gas) Owner of impacted well: Talisman Energy (now owned by Advantage Oil & Gas) **Location of incident:** 75 kilometres northwest of Grand Prairie near BC border

Surface distance between wells: Approximately 1,600 metres

Subsurface distance between wells: 190 metres

Emulsified carbon dioxide Fracture fluid:

Less than 1 m³ **Volume released:**

Current status: Spill cleaned up. No public safety impacts. Minimal

environmental impact.